```
Sent:
             4/30/2015 8:21:36 PM
To:
             Carter Cole (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP
             (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Carter3]
Subject:
             Re: Possum Point Ash Pond C - Stop Log Sealing - April 30, 2015 Update
Thanks Carter!
Sent from my iPhone
> On Apr 30, 2015, at 8:10 PM, "Carter Cole (Generation - 34)" <carter.cole@dom.com> wrote:
> Doug,
            Mr. Ryan Nolasco of Crofton Diving provided several photographs of the completed work at the
Possum Point Ash Pond C Outlet Box, one of which I annotated and attached showing the west (downstream)
face of the Possum Point Ash Pond C stop logs at the end of Thursday, April 30. [NOTE: When viewing the attached file in Adobe Acrobat, I suggest that you "Zoom to Page Level."]
attached file in Adobe Acrobat, I suggest that you "Zoom to Page Level.
             I estimate that the Ash Pond C (water) level was at approximately 19.0' today.
>
            Based on my observations (refer to attached file) at the close of today, it is my
professional opinion that any MINOR observed seeping through stop logs NOW originates ABOVE the material
level (Elevation 17.7') as a result of Crofton Diving's work.
             Crofton Diving will attempt to remove the cured polyurethane resin (P.U.R.) that formed on
the east side of the Outlet Box (upstream of the stop logs) tomorrow and then demobilize.
             Crofton Diving will return to Possum Point on Monday, May 4 to work on sealing leaks at the
Ash Pond E Decant Structure.
> Please feel free to call me if you have any questions or need additional information
> Regards,
> Carter
> Carter L. Cole, P.E. [Virginia - 015258]
> Power Generation Engineering - Dominion Resources Services, Inc.
> Phone: 804-273-3049 (Office) 804-399-7820 (Cell)
> <PP Ash Pond C - West Face of Stop Logs - 4-30-15.pdf>
```

Doug Wight (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=DOUGLA7]

From: